

ESTIMATE



**339 MAPLEVIEW DR
CHARLOTTE, MI 48813**

Name/Address

City of Charlotte
111 W. Lawrence
Charlotte, MI 48813

PHONE: 517-652-1159

info@sommerbuilding.com

Date	Estimate No.	Project
09/27/16	2286	Stairway Repair

Item	Description	Quantity	Cost	Total
	South Stairs			
1	Setup And Tear Down Scaffold In South Stairwell		425.00	425.00
2	Material And Labor To Skim, Repair Or Remove And Replace Drywall As Needed In Stairwell		5,725.00	5,725.00
3	Material And Labor To Prep And Paint Stairwell Walls And Ceiling With 2 Coats Of Premium Ceramic Paint		4,440.00	4,440.00
4	Material And Labor To Prep And Paint Stair Skirting With Premium Oil Based Paint		575.00	575.00
5	Allowance For New LED Light Fixtures Installed		450.00	450.00
6	Option To Remove And Replace 2 Layers of Drywall On Southwall ADD \$ 1500.00		0.00	0.00
	North Stairs		0.00	0.00
1	Material And Labor To Prep And Re-Paint Stairwell Walls And Ceiling With Premium Ceramic Paint ADD \$ 2880.00			
2	Material And Labor To Prep And Paint Stair Skirting With Premium Oil Based Paint ADD \$575.00			
3	Install New LED Light Bulbs In Existing Fixtures ADD \$42.00		0.00	0.00
			Total	\$11,615.00